

Market Release Note

MRN-TS9100-722-B49

Product number: TS9100, TS9120, TS9120VM

Product description: Forcefield

Product version: TS9100 7.2.2 Build 49

Release date: 21 October 2019

Interlogix is pleased to announce the availability of Forcefield 7.2.2 Build 49. This release offers a number of resolved issues.

Resolved Issues

- Resolved issue where doors and floors may not be removed from the panel(s) when a Forcefield operator clears all doors and/or floors from a profile
- Resolved issues with configuration of second IP address on secondary network interface (where available)

Documentation and downloads

Marketing Collateral	Forcefield datasheet
	Tecom compatibility matrix
	TruVision video plugin datasheet
	Genetec video plugin datasheet
Technical Manuals	Forcefield Installation and Setup Manual *
	Forcefield Operators Manual *
	Forcefield External Interfaces Manual *
	Forcefield Licence Form
Software downloads	Visit www.interlogix.com.au/downloads to download the latest software and firmware versions.

* Requires secure login to access via Interlogix Support Portal

Known issues

- Serial printing to a third party system sometimes stops working when the system is under heavy load. As a result, occasionally the server will need to be restarted to resume functionality.
- USB keyboard and mouse must be connected on startup, otherwise they will not be detected.