

Market Release Note

MRN_TSX10000_TSX-1-77197

Product number:	TSX10000
Product description:	Discovery Control Panel Firmware
Product version:	TSX-1-77197
Release date:	18 th November 2024

This latest update for Tecom Discovery incorporates key improvements with feedback and collaboration from the Tecom community.

New Features

- Programming your Discovery panel is easier than ever, with significant updates to web interface functionality for installers.

Improvements

- Web UI updated to v1.1.74991-257:
 - New menu items for programming **Time & date, Inputs, Areas, RASs, DGPs, Alarm groups, Timers, System options, Auto reset, Comm BUS, Time zones, Soft timezones, User categories, Relays, Auto access/secure, Vaults, Area links, Input shunts, Battery test, Custom RAS message, Next service, Summary event flags, Panel macros, Area groups, Automation zones, Events, Holidays, and Discovery name.**
 - Viewing the status of a Communication path from the Dashboard widget now includes a shortcut icon to edit the Communication path settings.
- Support for entity names/descriptions in **Soft timezones, Auto access/secure, Area links, Input shunts, Floors, and Holiday types.**
- The firmware update process has been optimised, which will significantly reduce the time required to complete future updates, keeping downtime to a minimum.

Resolved Issues

- RS-485 comm devices are now correctly de-pollled when performing a factory default through the keypad.
- Door group 255 now correctly downloads to devices on the Comm 2 RS-485 bus.
- Resolved issue where daylight savings may not correctly adjust the clock in certain conditions.
- Resolved issue preventing users from being able to login to the web interface when they had a start date and/or end date configured.

- The web interface now correctly displays all supported programming entities.
- Resolved an issue where inputs on a TS1061 Dual Wiegand Interface connected to a Discovery control panel could incorrectly change state in certain conditions.
- Resolved issue where input type 12 could impact other areas in certain conditions.
- Resolved some issues affecting names of alarm groups, comm paths, and other entities.

Documentation and Downloads

Marketing Collateral	End User Brochure
Firmware Download	Firmware available from the Aritech resources page .

Known issues

- Some CTPlus diagnostics are not working correctly when CTPlus is connected to Discovery via UltraSync. This will be resolved in a future update.
- Not compatible with TS0866, TS0867, or TS0869 intelligent controllers.
- Not compatible with TS1053, TS1054, or TS1084 expansion modules.
- Some functionality and connections are currently reserved for future use, refer to the installation manual for more information.

Support

Please refer to the manuals and documentation on the [Aritech Support Portal](#) for more information.

For technical support, we encourage you to contact your local point of sale or distributor for all technical support calls. Alternatively, you can log a support call on the [Aritech Support Portal](#).