

Market Release Note

MRN_TSX10000_TSX-1-77197

Product number: TSX10000

Product description: Discovery Control Panel Firmware

Product version: TSX-1-77197

Release date: 18th November 2024

This latest update for Tecom Discovery incorporates key improvements with feedback and collaboration from the Tecom community.

New Features

- Programming your Discovery panel is easier than ever, with significant updates to web interface functionality for installers.
- Web UI updated to v1.1.74991-257:
 - New menu items for programming **Time & date**, **Inputs**, **Areas**, **RASs**, **DGPs**, **Alarm groups**, **Timers**, **System options**, **Auto reset**, **Comm BUS**, **Time zones**, **Soft timezones**, **User categories**, **Relays**, **Auto access/secure**, **Vaults**, **Area links**, **Input shunts**, **Battery test**, **Custom RAS message**, **Next service**, **Summary event flags**, **Panel macros**, **Area groups**, **Automation zones**, **Events**, **Holidays**, and **Discovery name**.
 - Viewing the status of a Communication path from the Dashboard widget now includes a shortcut icon to edit the Communication path settings.
- Support for entity names/descriptions in **Soft timezones**, **Auto access/secure**, **Area links**, **Input shunts**, **Floors**, and **Holiday types**.
- The firmware update process has been optimised, which will significantly reduce the time required to complete future updates, keeping downtime to a minimum.

Resolved Issues

- RS-485 comm devices are now correctly de-polled when performing a factory default through the keypad.
- Door group 255 now correctly downloads to devices on the Comm 2 RS-485 bus.
- Resolved issue where daylight savings may not correctly adjust the clock in certain conditions.
- Resolved issue preventing users from being able to login to the web interface when they had a start date and/or end date configured.



- The web interface now correctly displays all supported programming entities.
- Resolved an issue where inputs on a TS1061 Dual Wiegand Interface connected to a Discovery control panel could incorrectly change state in certain conditions.
- Resolved issue where input type 12 could impact other areas in certain conditions.
- Resolved some issues affecting names of alarm groups, comm paths, and other entities.

Documentation and Downloads

| | |
|-----------------------------|--|
| Marketing Collateral | End User Brochure |
| Firmware Download | Firmware available from the Aritech resources page . |

Known issues

- Some CTPlus diagnostics are not working correctly when CTPlus is connected to Discovery via UltraSync. This will be resolved in a future update.
- Not compatible with TS0866, TS0867, or TS0869 intelligent controllers.
- Not compatible with TS1053, TS1054, or TS1084 expansion modules.
- Some functionality and connections are currently reserved for future use, refer to the installation manual for more information.

Support

Please refer to the manuals and documentation on the [Aritech Support Portal](#) for more information.

For technical support, we encourage you to contact your local point of sale or distributor for all technical support calls. Alternatively, you can log a support call on the [Aritech Support Portal](#).