

## Market Release Note

MRN-TS1053-005

---

Product number: TS1053

Product description: Tecom 3G Communication Module

Product version: V01-01-31099

Affected parts: TS1053

Release date: 17 January 2019

---

Interlogix announces the immediate availability of the latest firmware for the Tecom 3G Communication Module.

**IMPORTANT NOTE: Please ensure that panel firmware V10-06.19251 or higher is installed prior to upgrading your 3G Communication Module.**

## Resolved Issues

- Resolved issue where module could lock up when network issues were present. TS1053 can now monitor network status and connectivity, and take action if required.

## Documentation

<b>Marketing Collateral</b>	<a href="#">3G Communication Module Datasheet (TS1053)</a>
	<a href="#">3G Communication Module Data Usage Information</a>
	<a href="#">Tecom Hardware Compatibility Matrix</a>
<b>Technical Manuals</b>	<a href="#">Tecom 3G Communication Module Installation Sheet</a>
<b>Firmware Download</b>	<a href="#">3G Communication Module firmware V01-01.31099 (ZIP)</a>
	<a href="#">3G Communication Module firmware V01-01.31099 (SREC)</a>

All downloads can be found at [www.interlogix.com.au/downloads](http://www.interlogix.com.au/downloads)

## Known issues

- Dual SIM is not currently enabled. At this time, only SIM1 can be used.
- Communications may not succeed if signal is weak. Ensure correct placement of antenna prior to installation.