

## Market Release Note

MRN-TS1066-V10-01.59090

---

Product number: TS1066, TS1066-4

Product description: Network Access Controller

Product version: V10-01.59090

Affected parts: n/a

Release date: 28<sup>th</sup> September 2021

---

## New Features

- Combine lifts and doors on any Network Access Controller.

### How to upgrade your firmware

Firmware is available via CTPlus (installer software). You will need to download CTPlus from the [website](#) before you can proceed with installation and setup.

## IMPORTANT INFORMATION – BEFORE YOU BEGIN

Once you have downloaded CTPlus, you will be required to download the latest version firmware which is available via CTPlus.

A 'How to upgrade Network Access Controller firmware' document is available in the download section below to assist in this process.

## Documentation and Downloads

<b>Marketing Collateral</b>	<a href="#">Network Access Controller datasheet</a>
	<a href="#">Tecom Compatibility Matrix</a>
<b>Technical Manuals</b>	<a href="#">Network Access Controller Installation Manual</a>
	<a href="#">Network Access Controller Quick Programming Manual</a>
	<a href="#">How to upgrade Network Access Controller firmware</a>
<b>Firmware Download</b>	Firmware is available via the latest version of CTPlus
<b>Software Download</b>	To download CTPlus, please visit the downloads site at <a href="https://firesecurityproducts.com.au/downloads">firesecurityproducts.com.au/downloads</a>

## Known issues

- Not compatible with Challenger10 or Challenger V8 systems

## Support

Please refer to the manuals and documentation on the [Carrier Fire & Security Support Portal](#) for more information.

For technical support, we encourage you to contact [Hills Technical Support](#) for all technical support calls. Alternatively you can log a support call on the [Carrier Fire & Security Support Portal](#).